

## Popcorn Machine ET-POP6A-R Spare parts list and drawing

No.	Name
1	Top Roof
2	Back Panel
3	Left ,Right Panel
4	Front Panel Bracket
5	Front Glass Wing
6	Side Glass Wing
7	Top Inside Panel
8	Switch
9	Motor 110V,14W,15R/M
10	Magnet Ring
11	Light Bulb and Base,50W
12	Light Bulb Cover
13	Door Magnet
14	Kettle Bracket left
15	Kettle Bracket right
16	Kettle Panel
17	Kettle Panel Support
18	Stir Rod Arm
19	Stir Rod Tube
20	Stir Rod
21	Back Glass
22	Left/Right Side Glass
23	Kettle Lid /Pot Cover
24	Kettle Assembly
25	Right Door Hinge
26	Left Door Hinge
27	Door Hinge Clamp
28	Door Handle
29	Kettle Hinge Pin
30	Right/Left Door
31	Front Corner Aluminium Right
32	Back Corner Aluminium Left
33	Back Corner Aluminium Right
34	Back Glass Bracket
35	Left/Right Glass Bracket
36	Warming Deck
37	Drop Down Door
38	Warming Element clamp
39	Warming Element clamp Tube
40	Wire box cover
41	Machine Base
42	Old Maid /Kernel Tray
43	Warming Tray Element, 300W
44	Rubber feet
45	Warming Element limiter 55degree
N/M	Power Cord
N/M	Kettle Heating Element ,1000W
N/M	Inner Pot Assembly
N/M	Outer Pot Assembly
N/M	Pot heating limiter

